



07 November 2018

NOTIFICATION OF AWARD

Project Name: Road Climate Resilience Project (RCRP)
Country: Timor-Leste
Project No.: WORLD BANK IDA Credit No. 60120-TL

Bid/Contract Reference No.: : ICB//018/MOPTC-2017

Scope of Contract : **Upgrading and Maintenance of Dili-Ainaro Road**
Lot 2: Laurala – Solerema Section (km 12+000 to km 34+620)

Duration of Contract : a. Upgrading Works (Construction Phase) = 900 days
b. Defects Notification Period (DNP) = 365 days
c. Performance Based Maintenance (PBM) = 1,460 days

Evaluation Currency : United States Dollar (US\$)

Awarded Bidder

Name: China Wu Yi Co., Ltd.
Address: 4th Floor, Zhi Di Plaza, No.89 Wusi Road, Fuzhou, Fujian, P.R. China
Bid price at opening: US\$17,855,300.97
Evaluated bid price: US\$17,223,300.97 (Exclusive of provisional sum and contingency)
Contract Price: US\$17,855,300.97 (Inclusive of provisional sum and contingency)

Evaluated Bidders

- (1) Name: Guizhou Road & Bridge Group Co., Ltd.
Address: No.117 Zhonghua Mid-road, Yunyan District, Guiyang, Guizhou, China
Bid price at opening: US\$18,631,211.90
Evaluated bid price: US\$17,999,211.90 (Exclusive of provisional sum and contingency)
- (2) Name: Sinohydro Corporation Limited
Address: No.22 Chegongzhuang West Road, Haidian District, Beijing, 100048, China
Bid price at opening: US\$21,398,660.82
Evaluated bid price: US\$19,609,663.01 (Exclusive of provisional sum and contingency)
- (3) Name: China Geo-Engineering Corporation
Address: Building B, No.92 Xiangshan South Road, Haidian District, Beijing, China
Bid price at opening: US\$23,854,444.48
Evaluated bid price: US\$21,887,928.25 (Exclusive of provisional sum and contingency)
- (4) Name: PT. Istaka Karya (Persero)
Address: Jl. Iskandarsyah Raya No.66 Kebayoran Baru, Jakarta, Indonesia
Bid price at opening: US\$25,448,796.44
Evaluated bid price: US\$24,816,796.45 (Exclusive of provisional sum and contingency)

Rejected Bidders

- (1) Name: Kunming University of Science & Technology Design & Research Institute
Address: KUSTI Science Park Venture Building, 296#, Xuefu Road, Kunming, China
Bid price at opening: US\$26,020,068.10
Reason(s) for rejection: • Bidder failed to submit the correct format of Letter of Bid and instead submitted Letter of Technical and Price Bid separately; no Power of Attorney; no Mobilization Schedule; no Management Strategies and Implementation Plans (MSIP) to manage ESHS risks; and no Code of Conduct (ESHS); blank Forms FIN-3.3, FIN-3.4, EXP-

- 4.2(a) and EXP-4.2(b).
- Bidder is not responsive in accordance with Bidding Documents, Section I, ITB 11.1 and ITB 16.1.
- (2) Name: CBMI Construction Co., Ltd. & Chongqing Road Engineering Group Co., Ltd. (Joint Venture)
 Address: No. 7, Xingfudao, Fengrun District, Tangshan, China
 Bid price at opening: US\$25,255,570.84
 Reason(s) for rejection:
 - Bidder did not provide the (i) Management Strategies and Implementation Plans (MSIP) to Manage ESHS Risks, and (ii) Code of Conduct (ESHS)
 - Bidder is not responsive in accordance with Bidding Documents, Section I, ITB 11.1 and ITB 16.1.
- (3) Name: China Harbour Engineering Company, Ltd.
 Address: No.9 Chunxiu Lu, Dongzhimenwai, Beijing, China
 Bid price at opening: US\$23,074,687.00
 Reason(s) for rejection:
 - Bidder did not provide Mobilization Schedule requirements on (i) Monthly Equipment Utilization Schedule and (ii) Monthly Manpower Schedule of Key and Office Personnel
 - Bidder is not substantially responsive as per requirements of Bidding Documents, Section I, ITB 29.3, in particular, the requirements of Section III, 2. Evaluation, 2.1: Assessment of Adequacy of Technical Proposal with Requirements, and Section IV – Bidding Forms, Technical Proposal, Mobilization Schedule.
- (4) Name: China State Construction Engineering Corporation, Ltd.
 Address: No.15, Sanlihe Road, Haidian District, Beijing, China
 Bid price at opening: US\$24,422,015.49
 Reason(s) for rejection:
 - Bidder did not provide Mobilization Schedule requirements on Monthly Equipment Utilization Schedule.
 - Bidder did not provide the complete Form EQU for the required 14 key equipments (proposed only 8 key equipment out of the required 22 equipments)
 - Bidder is not substantially responsive as per requirements of Bidding Documents, Section I, ITB 29.3, in particular, the requirements of Section III, 2. Evaluation, 2.1: Assessment of Adequacy of Technical Proposal with Requirements, and Section IV – Bidding Forms, Technical Proposal, Mobilization Schedule.
- (5) Name: China Civil Engineering Construction Corporation
 Address: No.4, Beifengwo, Haidian District, Beijing, China
 Bid price at opening: US\$20,591,882.16
 Reason(s) for rejection:
 - Bidder did not provide Mobilization Schedule requirements on (i) Monthly Equipment Utilization Schedule and (ii) Monthly Manpower Schedule of Key and Office Personnel
 - Bidder is not substantially responsive as per requirements of Bidding Documents, Section I, ITB 29.3, in particular, the requirements of Section III, 2. Evaluation, 2.1: Assessment of Adequacy of Technical Proposal with Requirements, and Section IV – Bidding Forms, Technical Proposal, Mobilization Schedule.
- (6) Name: Chongqing International Construction Corporation (CICO)
 Address: No.40, Sixin Road, Yuzhong District, Chongqing, PRC
 Bid price at opening: US\$15,668,015.00
 Reason(s) for rejection:
 - Bidder did not provide Mobilization Schedule requirements on (i) Monthly Equipment Utilization Schedule and (ii) Monthly Manpower Schedule of Key and Office Personnel
 - Bidder failed to meet the requirements on Personnel. Bidder provided the time commitment in Forms PER-1 and PER-2 for each key personnel as 3 months which is not acceptable. Did not provide high level Gantt chart to confirm the time commitment of the proposed key personnel.
 - Bidder is not substantially responsive as per requirements of Bidding Documents, Section I, ITB 29.3, in particular, the requirements of Section III, 2. Evaluation, 2.1: Assessment of Adequacy of Technical Proposal with Requirements and Section IV – Bidding Forms, Technical Proposal, Mobilization Schedule.

- (7) Name: Shanghai Construction Group Co., Ltd.
Address: No.33, Fushan Rd, China (Shanghai) Pilot Free Trade Zone, China
Bid price at opening: US\$18,172,416.73
Reason(s) for rejection:
- Bidder failed to meet the requirement on Key Personnel for the position of Social and Resettlement Officer in PER-1.
 - Bidder is not substantially responsive as per requirements of Bidding Documents, Section I, ITB 29.3, in particular, the requirements of Section III, 2. Evaluation, 2.1: Assessment of Adequacy of Technical Proposal with Requirements



Director, National Procurement Commission